WHO WE ARE

Stromberg Carlson was founded by Alfred Stromberg and Androv Carlson in 1894, in Chicago, USA. They quickly established a reputation for creating durable products of high technological quality. Continuing this legacy of over a century is our mission.



CARE

When the battery runs out, charge for at least 30 minutes before using again.

Charge for 4 hours for a full charge.

Don't keep it plugged in all the time!







Do not hit




Do not expose to the sun





HOW TO RECYCLE

METAL



BATTERY

WARRANTY & SERVICE

SCAN THE QR CODE TO ACCESS THE WARRANTY AND CONTACT TECHNICAL SUPPORT.



stromberg.world/pages/warranty

STROMBERG



WHAT'S IN THE BOX










CONTROL **PANEL**

STAND BY: Unit will turn off automatically after 5 minutes if it is not in use.



WIRELESS CONNECTION

TO DISCONNECT:















WITH OTHER GROOVE MODEL





