

WHO WE ARE

Stromberg Carlson was founded by Alfred Stromberg and Androv Carlson in 1894, in Chicago, USA. They quickly established a reputation for creating durable products of high technological quality. Continuing this legacy of over a century is our mission.

CARE



When the battery runs out, charge for at least 30 minutes before using again.

Charge for 4 hours for a full charge.

Don't keep it plugged in all the time!



Do not get wet



Do not hit




Do not expose to the sun




Protect from the heat

HOW TO RECYCLE



WARRANTY

REGISTER YOUR PRODUCT IN OUR LIMITED WARRANTY WEB PAGE OR CONTACT US ABOUT PRODUCT INFROMATION



stromberg.world/pages/warranty


STROMBERG



CHUNK-2




WHAT'S IN THE BOX




CONTROL PANEL

 **STAND BY:** Unit will turn off automatically after 5 minutes if it is not in use.



BLUETOOTH CONNECTION



STROMBERG CONNECT

